

BTOS Release Notes

Style: B27-B38 ST8

Level: 8.1.2

August 26, 1987

BTOS 8.1 Release Notes 1

CONTENTS

Title	Page
NEW FEATURES.....	3
PRODUCT IMPROVEMENTS.....	3
KNOWN LIMITATIONS.....	8
Request File Loading.....	8
Optional Request File Loading During Standalone Utilities Installation.....	8
ECC Drives.....	9
Math Server.....	10
Adding Hardware Modules.....	10
Queue Manager/Spooler Limitations.....	10
Pascal 5.1 Programs Linked with Pascal 8087.fl5 (Math Co-Processor Only).....	11
Pascal on a B38 Workstation.....	11
PMOSS 1.0 Known Limitations.....	11
ISR Limitations.....	11
Math Co-Processor.....	12
Unsupported Interfaces.....	12
Multiple Run Files in the Same Partition.....	12
Parameter Management.....	12
Restrictions on Send and Psend.....	12
COED Facility.....	13
ServeSc.....	13
Customizer.....	13
KNOWN PROBLEMS.....	13
Incorrect Printer Configuration File..	14
B38 Cluster Bootstrap Procedure.....	14
Using ECC Disk Drives with an Earlier BTOS.....	14
Some RS-232 Applications on the DCX...	15
PMOSS 1.0 Known Problems.....	15
Startup ACTION-FINISH Problem.....	15

BTOS 8.1 Release Notes 2

AllocAreaSL.....15
BOOTSTRAP Command.....16

NEW FEATURES

The new features in this release are:

- B24 Low Cost Teller Workstation Support (Refer to the following documents:)

3641 1205 B24 TWS Software Design Specification

3641 1197 B24 TWS Software Functional Specification

PRODUCT IMPROVEMENTS

The major product improvements in this release are:

- A new parallel printer driver eliminates the known problems with the previous one.
- A much improved RS-422 Shared Resource Processor (SRP) protocol handler provides performance improvements of up to six times prior versions. Also, transmit underrun errors are now handled correctly.
- The Variable Length Parameter Block (VLPB) logic now returns an error code if the user attempts to enter a subparameter longer than 255 characters.

- The Executive now saves up to 1024 bytes of form fill-in information. The Executive stores this information in the VLPB as subparameters (of no more than 255 bytes) of parameter 0, starting with subparameter 2 and continuing until the last subparameter stored is less than 255 bytes in length.
- XBif is now nationalizable.
- The FILES command, on a passworded volume, now correctly returns erc 219 (access denied) when it fails to complete a full report because of protected files.
- In Executive input forms, the password is now deleted when the user deletes the caret ("^") with either the DELETE or the BACKSPACE key. Also, if the user attempts to overwrite the caret or to insert a space after the caret, the Executive simply beeps.
- An improved Hardware ID handler eliminates known compatibility problems.
- Bootstrap now boots correctly on the B27 workstation, and correctly changes the sys volume to floppy.
- XON/XOFF handshake on RS-232 communications now works correctly.
- MCR now works correctly, returning an error code when contents are discarded after 20 seconds.
- ACTION-OVERTYPE and video timeout now work on B27 and B22 work stations.

- Maintain File now warns the user and offers to CANCEL or FINISH if either the output file or the log file will overwrite an existing file.
- The BTOS operating system now ignores keystrokes entered before the keyboard translate tables are loaded. This eliminates an occasional erc 610 that occurred upon booting.
- The BTOS operating system now correctly handles the default node name.
- In debugger, search for byte pattern (CODE-O) now works correctly for all forms of address range.
- InitOverlay function now works correctly, even when very small overlays are requested.
- User File Editor now correctly handles a template with ten user environments.
- BTOS now correctly creates temporary directories ("<\$>"), even when the system volume is password protected.
- CODE-Z (Zoom Command) is now correctly rejected by the B27 editor on a B27 with color monitor.
- Calls to ReadCommLineStatus and WriteCommLineStatus no longer intermittently produce erc 62 when DcxServer is installed.

- Form feed Translation: The characters 08h, 09h, 0Ah, 0Ch, 0Dh (backspace, tab, line feed, form feed, carriage return, respectively) are considered 'special' character by the BTOS printer driver because certain attributes of the document being printed are affected by the printing of these characters. It is possible to translate these characters in BTOS release 8.1.2, but the following will occur when these characters are, in fact, translated:

Character-count tracking (i.e., the number of character 'debited' against the line currently being printed) is incremented by one for every character which is translated, even if the translation is one-to-many. This is necessary in order to prevent multi-byte escape sequences from truncating a line, while still tracking line count accurately when the translation tables are used for nationalization or wheel accomodation. Note that the normal effect of these characters on character-count tracking is different when translation is not performed on these characters (e.g., printing a line feed clears the character count instead of incrementing it and printing a tab increments the character count by more than one, depending on tab expansion specified).

No new line mapping will occur if the 0Ah (line feed) character is translated. It is assumed the user wishes to specify what character(s) will be emitted when this character occurs, and that the character may have some meaning other than 'end-of-print-line'.

No tab expansion will occur if the 09h (tab) character is translated.

No clearing of horizontal position will ever occur on encountering a character which has been translated.

Translating a character to itself (e.g., 0Ah = 0Ah) has no effect on printing, and does not qualify as translating the character.

KNOWN LIMITATIONS

If there is a workaround for any of these limitations, it is included in the discussion.

Request File Loading

Request file loading can cause BTOS to crash at boot time with an error 101. You can avoid this problem by examining the need for the utilities or applications that load excess request files. If the target system requires all loaded request files, you can customize BTOS and decrement the nPartitions and/or the nWsTotal parameter in the operating system assembly file until BTOS boots successfully.

Optional Request File Loading During Standalone Utilities Installation

To allow for successful loading of the operating system, you can rename or delete request files that are optionally loaded during installation of the Standalone Utilities. These request files are as follows:

Request.H.Sys	(Hardware ID)
Request.VP.Sys	(Telephone Server)
Request.XBif.Sys	(XBif Server)
Request.2.Sys	(DCXServer)
Request.PMOSS.Sys	(PMOSS)

Similarly, the following files are optionally loaded during Language Development software installation:

Request.Graphics.Sys (Graphics)
Request.Mouse.Sys (Mouse)

Note: To allow access to the system returning an error 101, boot that system off a bootable diskette or a master, rename the unnecessary request files, and then reboot locally.

ECC Drives

If you run IVOLUME to format a Winchester disk in ECC mode and specify a Crash File, you should enter the following bad spots:

cylinder/head/sector

where:

cylinder = 0
head = 0
sector = #2 through #15

For example, 0/0/#2, 0/0/#3 ... 0/0/#15.

You must enter these bad spots if you are using CrashDump.sys to study system crashes on BTOS 8.1.1 You do not need to mark these as bad spots if you do not specify a Crash file, or you only use Crash Dump.sys as a swap file for the Context Manager.

Math Server

Only the hardware Math Server is implemented in BTOS 8.1.2.

Adding Hardware Modules

Adding hardware modules on the bus can result in an error 101. Installing more servers from the executive level than memory allows can result in an error 430. You can use the same workarounds recommended for request file loading problems (previously described) to avoid these problems.

Queue Manager/Spooler Limitations

If You attempt to load more than the Queue Manager limit (10 queues, including the required SpoolerStatus.Queue), the system returns error 911 at the Executive level.

If your system returns error 420 (indicating that the Executive cannot initialize) and the system hangs after you install Spooler and execute the SPOOLER STATUS command, your system tried to use more than the defined number of real time clocks. To avoid this situation, either review your system requirements to remove system services or queues that use up your system real time clocks, or generate a custom operating system and increase the 'nPTiming' parameter in increments of 10 until no error occurs.

**Pascal 5.1 Programs Linked with
Pascal 8087.fls (Math Co-Processor Only)**

A Pascal 5.1 program linked with Pascal 8087.fls will not operate on a B38 math co-processor (MCP). (Pascal 5.1 does not use the B38 co_processor.)

Workaround: If the program requires the use of the 80287 co-processor, you must compile and link the program with Pascal 6.0. Or you must install the hardware Math Server.

Pascal on a B38 Workstation

A Pascal 4.0 or earlier program is not compatible with a B38 workstation.

Workaround: Recompile your program using Pascal 5.1 or 6.0, and relink with CTOS.lib 7.0.7 or 8.0/8.1 respectively.

PMOSS 1.0 Known Limitations

ISR Limitations

PMOSS 1.0 supports only the following two types of protected mode interrupt service routines (ISRs): raw RS-232 comm ISRs and programmable interval timer (PIT) ISRs. Raw ISRs for serial ports are not permitted to modify the SS register; doing so causes a general protection fault. A user written PIT ISR must not enable interrupts during its execution. The only permissible system calls in both raw comm ISRs and PIT ISRs are ReadCommLineStatus, WriteCommLineStatus, SetTimerInt, and ResetTimerInt.

Math Co-Processor

You Cannot use the 80287 math co-processor in a protected mode server.

Unsupported Interfaces

PMOSS does not support the Virtual Code Segment facility (or Overlay Manager). You must not use the "/o" linker option to link programs to be executed in protected mode.

Multiple Run Files in the Same Partition

PMOSS does not support multiple run files in the same partition (LoadTask, LoadInteractiveTask).

Parameter Management

PMOSS does not support parameter management for programs that create the Variable Length Parameter Block (VPLB) using RgParamInit.

Restrictions on Send and Psend

When used to send messages inter-task, Send and Psend have the following restrictions: The pMsg operand must either have a zero selector or be a pointer to a request block. The pointer to a request block must be that of an outstanding request originated by the task (by a Request or Request Direct) to which the pMsg is being sent. If the selector is a pointer, the sender must also place ercInterTaskSend (14106) in the ercRet field before doing the Send or Psend.

COED Facility

PMOSS does not support the COED facility.

ServeSc

PMOSS does not support the ServeSc object module procedure.

Customizer

When customizing a workstation for 15 workstations, specify %SET(nPartitions,12) instead of 25 in xxx.asm.

KNOWN PROBLEMS

This information is provided so that you can avoid the problem. These problems are listed in the Product Support Information Manual (PSIM); fix schedules will be maintained in the PSIMs.

Incorrect Printer Configuration File

The printer configuration default file for serial printers is incorrect in denoting that both the CTS and XON/XOFF protocols are handled. Though the BOTH option indicates the handling of both protocols, the default is actually CTS only.

Workaround: If a serial printer can perform only XON/XOFF protocol, then you must change the configuration file to stipulate XON/XOFF rather than BOTH.

B38 Cluster Bootstrap Procedure

Without operator intervention, B38 cluster bootstrap (cluster without local files or with local files on diskette only) loads only the B28 operating system (t2clstrxx.sys) instead of the B38 (t3clstrxx.sys). The default for the boot ROM on both the B28 and B38 operating systems are functionally the same.

Workaround: To circumvent loading a B28 operating system on a B38, use the spacebar or menu boot which requires entering the workstation type (231 or 232). `Ws23?>sysimage.sys` is for future development purposes, but you can use it interchangeably with the B28 current operating system.

Using ECC Disk Drives with an Earlier BTOS

ECC drives are supported in BTOS 8.0 and higher levels only. ECC formatted drives can be formatted under BTOS 7.0 (or earlier) but they are not capable of automatic error correction.

Caution: If you boot with BTOS 7.0 (or earlier) winchester disk drives that were formatted in ECC mode with BTOS 8.0 (or later), all data on the disk will be lost.

Workaround: Do not downgrade a system with ECC disk drives to a previous operating system without backing up data.

Some RS-232 Applications on the DCX

Hardware-dependent RS-232 applications won't run on the DCX. Since byte streams are device dependent, applications using byte streams will run on the DCX without modification.

Workaround: Convert device-dependent applications to use byte streams.

PMOSS 1.0 Known Problems

Startup ACTION-FINISH Problem

Using ACTION-FINISH at the instant of startup of a protected mode program can occasionally cause unpredictable results, including system crashes.

AllocAreaSL

The AllocAreaSL procedural interface (documented in the BTOS Protected Mode Programming Guide) returns a pointer whose offset is not necessarily zero. Replacing AllocMemorySL calls with AllocAreaSL calls can cause a crash 26 (illegal instruction) in REAL MODE on a B28/B38 if the offset of the allocated memory area's last byte is 0FFFFH and you attempt a word access for the last byte. An account of the Pascal compiler's code generation problems for protected mode is documented in the BTOS Protected Mode Programming Guide.

BOOTSTRAP Command

If you are using PMOSS and you want to boot your system, use the Reset switch. The BOOTSTRAP command may occasionally fail to reset all conditions necessary for PMOSS to run.

(ST8) Standalone Operating System 8.01.02.
B26 to B38

Seven diskettes (ST & SU) containing Standalone
Operating System

	BTOS Release Notes Level 8.1.2	
3027057	Field Communication Form	
1130838	User Guide to Fault Reporting	
5022148	BTOS Sort/Merge Operations Reference Manual	
5022148-001	BTOS Sort/Merge Operations Reference Manual PCN	
5026065	BTOS Protected Mode Programming Guide	
5026172	BTOS Protected Mode Operating System Server (PMOSS) Installation Guide	
5026222	BTOS Standard Software Operations Guide	
5026222-002	BTOS Standard Software Operations Guide PCN	
5026321	BTOS Status Codes Reference Manual	
5026321-001	BTOS Status Codes Reference Manual	PCN
5026321-002	BTOS Status Codes Reference Manual	PCN
5026339	BTOS Standard Software Operations Quick Reference Guide	
5026339-001	BTOS Standard Software Operations Quick Reference Guide	PCN
5026339-002	BTOS Standard Software Operations	
5026594	BTOS Editor Operations Guide	