

# SERVICE MANUAL CHANGES

## MANUAL IDENTIFICATION

**Model Number:** 64941A

**Date Printed:** April 1983

**Part Number:** 64941-90902

This supplement contains important information for correcting manual errors and for adapting the manual to instruments containing improvements made after the printing of the manual.

To use this supplement:

Make all ERRATA corrections.

Make all appropriate serial number related changes indicated in the tables below.

Serial Prefix or Number	Make Manual Changes	Serial Prefix or Number	Make Manual Changes
ALL			

## ERRATA

Page 6-7, replaceable parts list (last part number on page),

If 64100A Mainframe has serial prefix 2301A and a suffix of 03176 or greater, change A10A7 Shield Box Assembly part number from 64100-65501 to 64100-65502.

## CHANGE

Title page,

Change: Serial prefix from 2301A to 2429A

Page 6-4, replaceable parts list,

Change: A9 and A10, HP Part number from 09130-69600 to 09131-69600. This will include the drive electronics board (A9A2 and A10A2) when ordered.

## NOTE

If the 64100A mainframe has a serial prefix of 2301A or less, the replaceable part numbers for the 64941A Disc Drive and Drive Electronics board (A9, A9A2, A10, A10A2) will not change.

## NOTE

Manual change supplements are revised as often as necessary to keep manuals as current and accurate as possible. Hewlett-Packard recommends that you periodically request the latest edition of this supplement. When requesting copies quote the manual identification information from your supplement, or the model number and print date from the title page of the manual.





SERVICE MANUAL CHANGES

MANUAL IDENTIFICATION

Model Number: 64941A

Date Printed: April 1983

Part Number: 64941-90902

This supplement contains important information for correcting manual errors and for adapting the manual to instruments containing improvements made after the printing of the manual.

To use this supplement:

Make all ERRATA corrections.

Make all appropriate serial number related changes indicated in the tables below.

Serial Prefix or Number	Make Manual Changes	Serial Prefix or Number	Make Manual Changes
ALL			

▲ NEW ITEM

The Model 64941A Floppy Drive Control Board is now supported by the Bluestripe program. The Bluestripe pipeline contains replacement boards for 64000 options made by Hewlett-Packard. The replacement board for the Model 64941A is available at the factory. For additional information, contact your nearest Hewlett-Packard representative. The bluestripe replacement part number for the 64941A Floppy Drive Control Board is:

64941-69502

NOTE

Manual change supplements are revised as often as necessary to keep manuals as current and accurate as possible. Hewlett-Packard recommends that you periodically request the latest edition of this supplement. When requesting copies quote the manual identification information from your supplement, or the model number and print date from the title page of the manual.

